

Disconnect everything from the control box, including the power cord. Wait a few minutes and then follow the steps listed below:

- 1.Plug the power into the control box and ensure cabling is secure.
- 2.Plug the legs into the control box and ensure cabling is secure.
- 3.Plug the hand switch into the control box and ensure cabling is secure.

Everything should now be plugged back in. Now you must zero out the base (put into lowest position):

- 1.Hold the down button down until both legs reach their lowest position.
- 2.Once the table has stopped moving, release the down button and **press and hold the down button again until the table makes a small movement down and pops back up.** (This could take up to 12 seconds to occur)

Identifying components correctly

Independent Beam with Motor



Motor OR Drive



Motor Bushing



Control Box or Control Unit



Hand Control Hand Set



Leg Column



Leg Spindle

